



Motherboard Logo Program (MLP)

Intel® Desktop Board

DQ963GS

MLP Report

1/9/2007

Purpose:

This report describes the DQ963GS Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel and Pentium are registered trademarks of Intel Corporation in the United States and other countries.

* Other names and brands may be claimed as the property of others.

Copyright © 2007, Intel Corporation. All rights reserved.

Contents

- Introduction 4**
 - Terms and Definitions 4
- Desktop Board Configuration 5**
 - Desktop Board DQ963GS Final Configuration Report: Completion of MLP 5
 - Board Information 5
 - Product Code 5
 - Processor 5
 - System Memory 5
 - Power Management 5
 - Operating System Tested 5
 - Onboard Integrated Devices and Driver 6
 - Hardware Compatibility Tests Used (HCT) 6
 - Errata and Contingencies 7
 - Test Notes 7

Introduction

Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
HCT	Hardware Compatibility Tests
MLP	Motherboard Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.msp

Desktop Board Configuration

Desktop Board DQ963GS Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

Board Information

Product Code ¹	BIOS String/Model	Technologies NOT Logo'd (yet)
DQ963GS	MQ96510J.86A.0816.2006.0716.2308	N/A - all technologies logo'd
Processor		
Speed	3.8 GHz	
Family	Pentium® 4	
Bus Speed	800 MHz	
Form Factor	LGA775	
Connector Type	LGA775 Socket	
System Memory		
Amount Installed	4096 MB MB	
Speed	Dual Channel, DDR2, 800	
Memory Type	DIMM	
Connector Type	DDR2, 240 Pin	
Power Management		
BIOS Setting	S3	
Operating System Tested		
	Check Tested	Comments
Windows XP Pro	<input checked="" type="checkbox"/>	Service Pack 2
Windows XP Pro 64-bit	<input checked="" type="checkbox"/>	Service Pack 1

¹ These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

Onboard Integrated Devices and Driver

Technology	OS	Version
Chipset Update Utility Intel® Chipset Software Utility	Windows XP Pro	8.0.1.1002
	Windows XP Pro 64-bit	8.0.1.1002
Graphics Intel® Graphics Media Accelerator	Windows XP Pro	6.14.10.4624
	Windows XP Pro 64-bit	6.14.10.4642
Audio Sigmatel	Windows XP Pro	5.10.5067.0
	Windows XP Pro 64-bit	5.10.5067.0
LAN Intel® PRO Network Connections	Windows XP Pro	9.4.17.0
	Windows XP Pro 64-bit	9.4.17.0
Advance Fan Speed Control Intel® Quiet System Technology	Windows XP Pro	2.0.15.1110
	Windows XP Pro 64-bit	2.0.15.1110

Hardware Compatibility Tests Used (HCT)

Microsoft website: <http://www.microsoft.com/whdc/hwtest/system/default.aspx?area=SysSrv-dsktp>. Please check regularly for test kit updates. Not responsible for broken links caused by changes to Microsoft's Web Site.

Operating Systems	Notes	HCT
Windows XP Pro Windows XP Pro 64-bit	HCT 12.1.01 for Windows XP SP2	HCT 12.1.01 Test Procedure and Readme Downloads

Errata and Contingencies

Operating System	Failing Test	ID Number	Type	Error Description
Windows XP Pro Windows XP Pro 64-bit	PCI Compliance	1403	Errata	SEV2 : FAIL: 4.59.1 - Bits 07:02 in the PMCSR are reserved and must always return 0.
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1399	Errata	GetConfigDefault: Response == 0x80000000B7031110 ... GetConfigDefault(F1F): Response == 0x0006F6E4B7031110 Error: Codec must either respond to F1F control identically to F1C or respond with 0
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1457	Errata	Error: Location field can not be 0. Error: ConnectionType field can not be 0. Error: Color field can not be 0. Error: DefaultAssociation field can not be 0.
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1388	Errata	Error: If the DefaultAssociation is set to 0x0F, then the Sequence number must be 1. Error: Sequence field can not be 0.
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1398	Errata	Global Control = 0x00000001 Accept Unsolicited Response Enable -UNSOL = 0x00 FAIL : Accept Unsolicited Response Enable -UNSOL is not RW FAIL: Accept Unsolicited Response Enable -UNSOL is not RW
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	2965	Incident	SDx Input Stream Descriptor Control_3 = 0x04 Assertion Testing for Read Write: Testing... Assertion Testing for Read Write: FAILED.
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1463	Errata	Start Case: ID 37:2 : Codec Tests\RequiredVerbSupport:[date of test] ... (several lines of function calls and returns) End Case: ID 37:2 : FAIL : Codec Tests\RequiredVerbSupport : [date of test]

Test Notes

Operating System	Test	Description